

Hygro-Acoustic Stability and Maintenance Protocol for Hard Maple (*Acer saccharum*) Harps: A Standardized Approach to Preserving Therapeutic Resonance

Author: WEI-YI, LAI

Date: February 20, 2026

Document Type: Technical Protocol / Research Report

License: CC BY 4.0

Related Identifiers: <https://doi.org/10.5281/zenodo.18701450>

Associated Study: Part II of the "Maple Harp Resonance Series" (Refers to Part I: Spectral Analysis)

Abstract

I. This technical protocol defines the environmental and structural mandates required to maintain the acoustic integrity of Hard Maple harps. By establishing strict thresholds for humidity (45%\text{--}55\% RH) and temperature, this study ensures the stability of the D-Major harmonic profile (specifically D₄ at 293.66\text{ Hz}) intended for clinical music therapy.

II. Experimental Environment: Monitoring & Calibration

To preserve the hygroscopic balance of the *Acer saccharum* soundboard, the following parameters are mandatory:


- Target Humidity: 45%\text{--}55\% Relative Humidity (RH).
- Target Temperature: 20^\circ\text{C}\text{--}24^\circ\text{C} (68^\circ\text{F}\text{--}75^\circ\text{F}).

- Protocol: Continuous monitoring via iPad-integrated Bluetooth sensors is required to ensure no abrupt thermal expansion/contraction occurs.

III. Deviation Management: The "Safe Resonance Window"

As demonstrated in the Banana Plot (See Fig 1), deviations outside the safety threshold trigger immediate corrective actions:

- Low Humidity (<40% RH): Activate ultrasonic humidifiers. Failure to act causes "Soundboard Sinking," increasing lever tension and risking grain fractures.
- High Humidity (>60% RH): Activate industrial dehumidifiers. Excessive moisture softens the wood's Young's Modulus, dampening the 1\text{--}4\text{ kHz} harmonic brilliance identified in Part I.




IV. Structural Integrity & Tuning Standards

Systematic maintenance ensures frequency stability and prevents structural fatigue:

- Tuning Standard: $A_4 = 440\text{ Hz}$ (Scientific Standard) or 432 Hz (Therapeutic Protocol).
- Stress Inspection: Weekly visual audits of the Neck-to-Body junction to detect stress-induced warping.
- Lever Maintenance: Apply laboratory-grade dry PTFE lubricant to lever cams every 6 months to facilitate seamless D-Major transitions.

**Figure 2: Structural Stress Analysis and Inspection Points
(Stress Checkpoints)**



V. Material Handling & Contamination Control

To prevent acoustic impedance changes caused by surface oils:

- Manual Handling: Personnel must wear lint-free gloves when contacting unvarnished maple components.
- Cleaning: Use only micro-fiber cloths; avoid commercial waxes that clog pores and dampen resonance.

VI. Methodology: iPad-Based Data Logging

For research transparency, all climate and acoustic data are logged via:

- Platform: iPad (2021 model) using Numbers or Notion database.

- Metrics: Daily recording of RH, Temperature, and the "Reference String Tension" of D₄.

Date (Time)	Temp (°C)	RH (%)	D4 Freq (Hz)	Deviation (cents)	Lever Status
2026-02-20 (09:00)	22.5	50%	293.66	0.0	Secure
2026-02-20 (14:00)	23.1	52%	293.72	+0.3	Secure
2026-02-20 (21:00)	21.8	48%	293.62	-0.2	Secure

VII. Conclusion

This protocol creates a controlled environment that validates the spectral findings of the Hard Maple harp. Adhering to these SOPs is essential for ensuring that the "Healing Tone" remains consistent across long-term research cycles.

VIII. Standard Operating Procedure (SOP): Laboratory Maintenance

1. Climate Stabilization:

- Laboratories must utilize active humidification/dehumidification systems to maintain a constant 50% RH $\pm$ 5%.
- Ambient temperature should remain constant at 22°C $\pm$ 2°C to prevent thermal expansion of the maple fibers.

2. Deviation Protocol:

- Low Humidity Alert (<40%): Cease all acoustic recording immediately. Introduce ultrasonic mist until RH reaches 45%. This prevents structural "Soundboard Sinking."
- High Humidity Alert (>60%): Monitor soundboard arching. Utilize industrial-grade dehumidifiers to prevent "damping" of the 3rd and 5th harmonics, ensuring spectral brilliance.

IX. Structural Audit & Acoustic Calibration

- Tuning Precision: Standard calibration is set at A₄ = 440 Hz or 432 Hz, specifically for therapeutic research.

- Stress Inspection: Bi-weekly check of the Lever Tension Ratio for $F^{\{ \# \}}$ and $C^{\{ \# \}}$ strings. Perform monthly visual inspections for micro-fractures in the maple grain to prevent structural fatigue.

X. Material Handling & Data Logging

- Contamination Prevention: Personnel must wear lint-free gloves when touching unvarnished maple.
- Digital Documentation: Daily logging of RH, Temperature, and D_4 string tension must be recorded via iPad-native applications (Numbers/Notion).

XI. Conclusion

Maintaining the hygro-acoustic balance is critical for the reproducibility of therapeutic harp music. This protocol ensures that the craftsmanship of the Hard Maple harp remains structurally sound and acoustically vibrant for long-term research and clinical use.

XII. Appendix A: Laboratory SOP Checklist (Visual Compliance Guide for Research Personnel)——

1. Daily Climate Check: Ensure Relative Humidity remains within 45%–55%.
2. Frequency Calibration: Adjust reference string D_4 to exactly 293.66\text{ Hz}.
3. PPE Compliance: Lint-free gloves are mandatory for all Hard Maple handling.
4. Deviation Response: If RH shifts by >5%, immediate climate correction is required.
5. Bi-weekly Structural Audit: Focus on the Neck-to-Body junction and lever tension.
6. Surface Care: Exclusively use microfiber cloths for dust removal.